

# Vehicle Inspection Report

**Agreement No:**

**Reg:** HN13MZL

**CN:** VF12RFL1H49449312

Report Date: 26/07/2017 6:54PM

**NAMA Grade:** 2

|              |                             |               |             |                  |            |
|--------------|-----------------------------|---------------|-------------|------------------|------------|
| Make:        | Renault                     | Fuel:         | D           | Date First Reg:  | 31/07/2013 |
| Model:       | Captur-que 1.5 M-nav Energy | Transmission: | Manual      | No Keepers:      | 1          |
| Engine Size: | 1.5                         | Gears:        | 5           | Colour:          | Orange     |
| Doors:       | 5                           | Mileage:      | 39733       | Soft Top:        | No         |
| Body Type:   | Hatchback                   | Declaration:  | Not Checked | Taxi/Private Hr: | No         |
| Vendor:      | RCI Vision                  | Yr of Manu:   | 2013        | Acc Damage:      | No         |
| Other:       |                             |               |             |                  |            |


| Extras            |     | Tyres                   |             | Miscellaneous       |            |
|-------------------|-----|-------------------------|-------------|---------------------|------------|
| Cassette Stereo:  | No  | Make                    | Tread (mm): | Service History:    | Full       |
| CD Player:        | No  | Right Front: Other      | 3           | Date Last Serviced: | 17/07/2017 |
| Sunroof:          |     | Left Front: Other       | 3           | Registration Doc:   | Here       |
| Electric Windows: | 4   | Right Rear: Continental | 5           | MOT:                |            |
| Air Conditioning: | Yes | Left Rear: Continental  | 5           | Date of Expiry:     |            |
| Cruise Control:   | Yes | Spare:                  | No          | Taxed To:           |            |
| Power Steering:   | Yes | Wheel trims:            |             | Keys:               | Yes        |
| Alloy Wheels:     | Yes |                         |             | Master:             | Yes        |
| Metallic Paint:   | Yes |                         |             | Spare:              | Yes        |
| Leather:          | No  |                         |             | No. Keys:           | 2          |
|                   |     |                         |             |                     |            |



**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

| Damage Location      | Fault                | Damage                | Qty | Cost                         | Total   |
|----------------------|----------------------|-----------------------|-----|------------------------------|---------|
| Bumper Front         | Chipped              | Touch In Smart Repair | 1   | £12.00                       | £12.00  |
| Wheel osf            | Corroded             | Refinish              | 1   | £40.00                       | £40.00  |
| Door Mirror Glass os | Broken               | Replace               | 1   | £0.00                        | £0.00   |
| Bonnet               | Poor Previous Repair | Refinish              | 1   | £113.00                      | £113.00 |
|                      |                      |                       |     | Damage Cost Total:           | £165.00 |
|                      |                      |                       |     | Damage Cost Total (Inc VAT): | £198.00 |



**osf wing mirror**

Comments:  
previous repairs visible, boot divider missing,

Print: David Murphy  
Date: 25/07/2017

| CAP        |       |
|------------|-------|
| Cap Code:  | 60783 |
| Cap Clean: | 0     |
| Average:   | 0     |
| Below:     | 0     |
| Reserve:   | 0     |