

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Rear	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£24.00
				Damage Cost Total (Inc VAT):	£28.80



Charge CABLE

Comments:

FULL ELECTRIC VEHICLE SUBJECT TO A BATTERY HIRE AGREEMENT,
SERVICE LIGHT REMAINS ON, Previous repairs visible

Print: David Murphy

Date: 19/07/2017

DM

CAP

Cap Code:	
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0