



Damage Location	Fault	Damage	Qty	Cost	Total
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
Seat Base Cover osf	Burn	Interior Smart Repair	1	£40.00	£40.00
Door nsr	Dented	PDR Smart Repair	1	£20.00	£20.00
Qtr Panel osr	Scratched	Machine Polish	1	£12.00	£12.00
Seat Base Cover nsr	Burn	Interior Smart Repair	1	£40.00	£40.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel osr	Scratched	Refinish	1	£40.00	£40.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£188.00
				Damage Cost Total (Inc VAT):	£225.60

Comments:  
previous repairs visible

Print: David Murphy  
Date: 24/07/2017

DM

CAP	
Cap Code:	58072
Cap Clean:	5250
Average:	4850
Below:	4450
Reserve:	0