

Vehicle Inspection Report

Agreement No:

Reg: UFZ3052

CN: VF12RFA1H51135985

Report Date: 30/01/2017 6:28PM

NAMA Grade: 2

Make: Renault	Fuel: P	Date First Reg: 13/08/2014
Model: Captur D-que 0.9 M-nav Nrg	Transmission: Manual	No Keepers:
Engine Size: 0.9	Gears: 5	Colour: Black And Orang
Doors: 5	Mileage: 18576	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Michelin	1
Left Front:	Other	0
Right Rear:	Michelin	3
Left Rear:	Michelin	3
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	None
Date Last Serviced:	
Registration Doc:	None
MOT:	No
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	No
No. Keys:	1



Front Angle



Rear Angle



Interior



Speedo Reading


Damage Location	Fault	Damage	Qty	Cost	Total
Door osf	Poor Previous Repair	Refinish	1	£113.00	£113.00
Tyre osf	Less Than 1.6mm	Replace	1	£0.00	£0.00
Wiper osf	Broken	Replace	1	£0.00	£0.00
Wiper osf	Broken	Replace	1	£0.00	£0.00
Tyre nsf	Less Than 1.6mm	Replace	1	£0.00	£0.00
				Damage Cost Total:	£113.00
				Damage Cost Total (Inc VAT):	£135.60

Comments:

service light remains on, require the two front tyres to be replaced, requires new wiper blades on front of vehicle

Print: David Murphy

Date: 19/01/2017



CAP

Cap Code: 60777
 Cap Clean: 8375
 Average: 7850
 Below: 7350
 Reserve: 8200