

Vehicle Inspection Report

Agreement No:

Reg: VFZ4508

CN: VF13FL00251991156

Report Date: 14/02/2017 11:43AM

NAMA Grade: 2

Make: Renault	Fuel: D	Date First Reg: 16/12/2014
Model: Trafic 1.6 SI27 Business +	Transmission: Manual	No Keepers:
Engine Size: 1.6	Gears: 6	Colour: White
Doors: 5	Mileage: 59042	Soft Top: No
Body Type: Van	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	Tyres	Miscellaneous
Cassette Stereo: No	Make	Service History: Full
CD Player: No	Tread (mm):	Date Last Serviced: 14/07/2016
Sunroof:	Right Front: Other 4	Registration Doc: None
Electric Windows: 2	Left Front: Other 4	MOT:
Air Conditioning: Yes	Right Rear: Continental 4	Date of Expiry:
Cruise Control: No	Left Rear: Continental 4	Taxed To:
Power Steering: Yes	Spare: Yes	Keys: Yes
Alloy Wheels: No	Wheel trims:	Master: Yes
Metallic Paint: No	Interior Condition	Spare: Yes
Leather: No	Clean: Odour/Smoked in?: No Valet:	No. Keys: 2
	Other:	



Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Tailgate	Dented	PDR Smart Repair	1	£20.00	£20.00
Qtr Panel osr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Screen Front	Chipped	Replace	1	£0.00	£0.00
Qtr Panel osr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Door Mirror Assy osf	Scuffed (Unpainted)	Other	1	£0.00	£0.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Qtr Panel osr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Qtr Panel osr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£154.00
				Damage Cost Total (Inc VAT):	£184.80



front bumper



front screen

Comments:
front screen chipped would need replaced

Print: David Murphy
Date: 07/02/2017

DM

CAP	
Cap Code:	E1586
Cap Clean:	7625
Average:	7050
Below:	6050
Reserve:	0