

Vehicle Inspection Report

Agreement No:

Reg: THZ1340

CN: UU15SDAAC52309080

Report Date: 22/02/2017 8:48AM

NAMA Grade: 2

Make: Dacia	Fuel: P	Date First Reg: 26/02/2015
Model: Sandero 0.9 way Laureate	Transmission: Manual	No Keepers:
Engine Size: 0.9	Gears: 5	Colour: Black
Doors: 5	Mileage: 14933	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	2
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	No
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Goodyear	3
Left Front:	Goodyear	3
Right Rear:	Goodyear	4
Left Rear:	Goodyear	4
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?:	Valet:
Other:		

Miscellaneous	
Service History:	Full
Date Last Serviced:	03/02/2017
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	No
No. Keys:	1




Front Angle



Rear Angle



Interior




Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Door osf	Scratched	Machine Polish	1	£12.00	£12.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Wheel Trim nsf	Missing	Replace	1	£0.00	£0.00
Wing nsf	Dented	PDR Smart Repair	1	£20.00	£20.00
Bumper Rear	Dented	Refinish	1	£86.00	£86.00
Door nsf	Scratched	Machine Polish	1	£12.00	£12.00
Bonnet	Dented	PDR Smart Repair	1	£20.00	£20.00
Door nsr	Scratched	Machine Polish	1	£12.00	£12.00
Qtr Panel nsr	Dented	PDR Smart Repair	1	£20.00	£20.00
Door Mirror Assy nsf	Scratched (Painted)	Other	1	£0.00	£0.00
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
				Damage Cost Total:	£280.00
				Damage Cost Total (Inc VAT):	£336.00



rear bumper



front bumper

Comments:

STOP WARNING LIGHT REMAINS ON, need of through vallet

Print: David Murphy

Date: 21/02/2017

DM

CAP	
Cap Code:	58973
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0