

# Vehicle Inspection Report

**Agreement No:**

**Reg:** HXZ1802

**CN:** SJNFAAZE0U6027001

Report Date: 13/03/2017 6:09PM

**NAMA Grade:** 1

Make: Nissan	Fuel:	Date First Reg: 29/01/2015
Model: Leaf Acenta	Transmission: Automatic	No Keepers:
Engine Size: ELECTRIC	Gears:	Colour: Red
Doors: 5	Mileage: 18583	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		


Extras	Tyres	Miscellaneous
Cassette Stereo: No	Make	Service History: Full
CD Player: Yes	Tread (mm):	Date Last Serviced: 21/01/2016
Sunroof:	Right Front: Bridgestone 3	Registration Doc: Here
Electric Windows: 4	Left Front: Bridgestone 3	MOT:
Air Conditioning: Yes	Right Rear: Bridgestone 3	Date of Expiry:
Cruise Control: Yes	Left Rear: Firestone 2	Taxed To:
Power Steering: Yes	Spare: No	Keys: Yes
Alloy Wheels: Yes	Wheel trims:	Master: Yes
Metallic Paint: No	Interior Condition	Spare: Yes
Leather: No	Clean: Odour/Smoked in?: No Valet:	No. Keys: 2
	Other:	




**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Wing nsf	Scratched	Machine Polish	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Door osf	Dented	PDR Smart Repair	1	£20.00	£20.00
Door nsf	Scratched	Machine Polish	1	£12.00	£12.00
				Damage Cost Total:	£68.00
				Damage Cost Total (Inc VAT):	£81.60



**3kw charge cable**

Comments:  
FULL ELECTRIC VEHICLE 3.3kw model

Print: David Murphy  
Date: 07/03/2017

CAP

Cap Code: 60549  
Cap Clean: 8575  
Average: 8000  
Below: 7450  
Reserve: 8550