

# Vehicle Inspection Report

**Agreement No:**

**Reg:** PFZ7886

**CN:** VF12RFL1H49532836

Report Date: 15/03/2017 4:05PM

**NAMA Grade:** 1

Make: Renault	Fuel: D	Date First Reg: 29/10/2013
Model: Captur 1.5 d-que S M-nav Nrg	Transmission: Manual	No Keepers:
Engine Size: 1.5	Gears: 5	Colour: Cream And Black
Doors: 5	Mileage: 35451	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2013	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	5
Left Front:	Other	4
Right Rear:	Michelin	2
Left Rear:	Michelin	3
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	20/06/2015
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



**Front Angle**



**Rear Angle**



**Interior**




**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Door nsf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Scratched	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£36.00
				Damage Cost Total (Inc VAT):	£43.20

Comments:  
previous repairs visible

Print: David Murphy  
Date: 13/03/2017



CAP	
Cap Code:	60785
Cap Clean:	8050
Average:	7525
Below:	7000
Reserve:	0