

Vehicle Inspection Report

Agreement No:

Reg: ASZ5022

CN: SJNFAAZE0U6026999

Report Date: 15/03/2017 4:08PM

NAMA Grade: 2

Make: Nissan	Fuel:	Date First Reg: 30/01/2015
Model: Leaf Acenta -3.3 kw	Transmission: Automatic	No Keepers:
Engine Size: ELECTRIC	Gears:	Colour: Red
Doors: 5	Mileage: 21377	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	

Tyres		
	Make	Tread (mm):
Right Front:	Michelin	3
Left Front:	Michelin	2
Right Rear:	Michelin	2
Left Rear:	Michelin	3
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	01/08/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



Front Angle



Rear Angle




Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Door nsr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£88.00
				Damage Cost Total (Inc VAT):	£105.60



3kw charge cable



nsf wheel

Comments:
FULL ELECTRIC VEHICLE 3.3 kw model

Print: David Murphy
Date: 13/03/2017

DM

CAP	
Cap Code:	60549
Cap Clean:	8475
Average:	7900
Below:	7350
Reserve:	0