

Vehicle Inspection Report

Agreement No:

Reg: GRZ3009

CN: VF15R5A0H49345550

Report Date: 29/03/2017 6:52PM

NAMA Grade: 3

Make: Renault	Fuel: P	Date First Reg: 31/07/2013
Model: Clio 0.9 D-que S M-nav Nrg	Transmission: Manual	No Keepers: 1
Engine Size: 0.9	Gears: 5	Colour: Blue
Doors: 5	Mileage: 36429	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2013	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Bridgestone	3
Left Front:	Bridgestone	3
Right Rear:	Michelin	2
Left Rear:	Michelin	2
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	14/07/2016
Registration Doc:	None
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Rear	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Door Mirror Assy nsf	Broken	Replace	1	£0.00	£0.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Wheel osr	Scratched	Refinish	1	£40.00	£40.00
Bonnet	Chipped	Machine Polish	1	£12.00	£12.00
Seat Back Cover osr	Torn	Interior Smart Repair	1	£40.00	£40.00
				Damage Cost Total:	£264.00
				Damage Cost Total (Inc VAT):	£316.80




nsf door mirror



nsf wheel



osf wheel



rear seat

Comments:
NSF door mirror lense broken

Print: David Murphy
Date: 27/03/2017

CAP	
Cap Code:	58074
Cap Clean:	6275
Average:	5825
Below:	5375
Reserve:	0