

# Vehicle Inspection Report

**Agreement No:**

**Reg:** WFZ1670

**CN:** SJNFAAZE0U6028058

Report Date: 11/04/2017 12:09PM

**NAMA Grade:** 2

Make: Nissan	Fuel:	Date First Reg: 27/02/2015
Model: Leaf Visia + - 3.3kw	Transmission: Automatic	No Keepers:
Engine Size: ELECTRIC	Gears:	Colour: White
Doors: 5	Mileage: 22997	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Michelin	4
Left Front:	Michelin	4
Right Rear:	Michelin	2
Left Rear:	Michelin	2
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	21/03/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




**Front Angle**



**Rear Angle**



**Interior**



**SPEEDO**

Damage Location	Fault	Damage	Qty	Cost	Total
Qtr Panel osr	Dented	PDR Smart Repair	1	£20.00	£20.00
Sill ns	Dented	Repair and Refinish	1	£138.00	£138.00
Door osf	Dented	PDR Smart Repair	1	£20.00	£20.00
Bumper Front	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Door osr	Dented	PDR Smart Repair	1	£20.00	£20.00
Qtr Panel nsr	Poor Previous Repair	Repair and Refinish	1	£138.00	£138.00
				Damage Cost Total:	£348.00
				Damage Cost Total (Inc VAT):	£417.60

Comments:  
FULL ELECTRIC VEHICLE 3.3kw MODEL

Print: David Murphy

Date: 04/04/2017

*DM*

CAP

Cap Code: 64320  
 Cap Clean: 8375  
 Average: 7800  
 Below: 7250  
 Reserve: 0