

Vehicle Inspection Report

Agreement No:

Reg: ASZ5925

CN: KMHSU81XSEU356407

Report Date: 11/04/2017 12:06PM

NAMA Grade: 2

Make:	Hyundai	Fuel:	D	Date First Reg:	15/08/2014
Model:	Santa 2.2 CRDi Fe Premium Se	Transmission:	Automatic	No Keepers:	1
Engine Size:	2.2	Gears:		Colour:	Black
Doors:	5	Mileage:	38184	Soft Top:	No
Body Type:	Estate	Declaration:	Not Checked	Taxi/Private Hr:	No
Vendor:	RCI Vision	Yr of Manu:		Acc Damage:	No
Other:					

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	Sliding
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	Yes

Tyres		
	Make	Tread (mm):
Right Front:	Other	3
Left Front:	Other	3
Right Rear:	Other	3
Left Rear:	Other	3
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	16/02/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Number Plate Front	Missing	Replace	1	£0.00	£0.00
Wheel osr	Corroded	Refinish	1	£40.00	£40.00
Number Plate Rear	Missing	Replace	1	£0.00	£0.00
Wheel nsr	Corroded	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£80.00
				Damage Cost Total (Inc VAT):	£96.00

Comments:
Vehicle has no number plates fitted

Print: David Murphy
Date: 11/04/2017

DM

CAP	
Cap Code:	
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0