

# Vehicle Inspection Report

**Agreement No:**

**Reg:** HXZ4561

**CN:** SJNFAAZE0U6030478

Report Date: 24/04/2017 12:29PM

**NAMA Grade:** 3

|                        |                          |                            |
|------------------------|--------------------------|----------------------------|
| Make: Nissan           | Fuel:                    | Date First Reg: 10/04/2015 |
| Model: Leaf Acenta 3.3 | Transmission: Automatic  | No Keepers:                |
| Engine Size: ELECTRIC  | Gears:                   | Colour: Red                |
| Doors: 5               | Mileage: 15721           | Soft Top: No               |
| Body Type: Hatchback   | Declaration: Not Checked | Taxi/Private Hr: No        |
| Vendor: RCI Vision     | Yr of Manu: 2015         | Acc Damage: No             |
| Other:                 |                          |                            |

| Extras            |     |
|-------------------|-----|
| Cassette Stereo:  | No  |
| CD Player:        | Yes |
| Sunroof:          |     |
| Electric Windows: | 4   |
| Air Conditioning: | Yes |
| Cruise Control:   | Yes |
| Power Steering:   | Yes |
| Alloy Wheels:     | Yes |
| Metallic Paint:   | No  |
| Leather:          | No  |

| Tyres        |          |             |
|--------------|----------|-------------|
|              | Make     | Tread (mm): |
| Right Front: | Michelin | 2           |
| Left Front:  | Michelin | 2           |
| Right Rear:  | Michelin | 3           |
| Left Rear:   | Michelin | 3           |
| Spare:       | No       |             |
| Wheel trims: |          |             |

| Interior Condition |                      |        |
|--------------------|----------------------|--------|
| Clean:             | Odour/Smoked in?: No | Valet: |
| Other:             |                      |        |


| Miscellaneous       |            |
|---------------------|------------|
| Service History:    | Full       |
| Date Last Serviced: | 09/04/2016 |
| Registration Doc:   | Here       |
| MOT:                |            |
| Date of Expiry:     |            |
| Taxed To:           |            |
| Keys:               | Yes        |
| Master:             | Yes        |
| Spare:              | Yes        |
| No. Keys:           | 2          |




**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

| Damage Location | Fault                | Damage                | Qty | Cost                         | Total   |
|-----------------|----------------------|-----------------------|-----|------------------------------|---------|
| Door nsr        | Poor Previous Repair | Refinish              | 1   | £113.00                      | £113.00 |
| Bonnet          | Chipped              | Touch In Smart Repair | 1   | £12.00                       | £12.00  |
| Qtr Panel nsr   | Poor Previous Repair | Repair and Refinish   | 1   | £138.00                      | £138.00 |
| Bumper Rear     | Poor Previous Repair | Refinish              | 1   | £86.00                       | £86.00  |
|                 |                      |                       |     | Damage Cost Total:           | £349.00 |
|                 |                      |                       |     | Damage Cost Total (Inc VAT): | £418.80 |



**3kw charge cable**



**nsr qtr**

Comments:  
FULL ELECTRIC VEHICLE 3.3kw Model, previous repairs visible

Print: David Murphy  
Date: 18/04/2017

DM

| CAP        |       |
|------------|-------|
| Cap Code:  | 60549 |
| Cap Clean: | 9350  |
| Average:   | 8725  |
| Below:     | 8125  |
| Reserve:   | 9350  |