

# Vehicle Inspection Report

**Agreement No:**

**Reg:** WFZ4091

**CN:** VF12FL11852202321

Report Date: 24/04/2017 4:04PM

**NAMA Grade:** 4

Make: Renault	Fuel: D	Date First Reg: 25/03/2015
Model: Traffic 1.6 LI29 Business+ Nrg -	Transmission: Manual	No Keepers:
Engine Size: 1.6	Gears: 6	Colour: White
Doors: 5	Mileage: 33531	Soft Top: No
Body Type: Van	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	Tyres	Miscellaneous
Cassette Stereo:	Make	Service History: None
CD Player:	Tread (mm):	Date Last Serviced:
Sunroof:	Right Front: Firestone 5	Registration Doc: None
Electric Windows:	Left Front: Goodyear 4	MOT:
Air Conditioning:	Right Rear: Goodyear 5	Date of Expiry:
Cruise Control:	Left Rear: Goodyear 5	Taxed To:
Power Steering:	Spare: Yes	Keys: Yes
Alloy Wheels:	Wheel trims:	Master: Yes
Metallic Paint:	Interior Condition	Spare: Yes
Leather:	Clean: Odour/Smoked in?: Yes Valet:	No. Keys: 2
	Other:	




**Front Angle**



**Rear Angle**

No Image

**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Sill ns	Dented	Refinish	1	£113.00	£113.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Roof Lining	Soiled	Interior Smart Repair	1	£40.00	£40.00
Bumper Rear	Dented	Repair and Refinish	1	£111.00	£111.00
Door nsr	Dented	PDR Smart Repair	1	£20.00	£20.00
Centre Console Front	Broken	Replace	1	£0.00	£0.00
Seat Base Cover osf	Burn	Interior Smart Repair	1	£40.00	£40.00
Fog Lamp osr	Broken	Replace	1	£0.00	£0.00
				Damage Cost Total:	£410.00
				Damage Cost Total (Inc VAT):	£492.00



passenger seat



center console



ns sill



nsr lense

Comments:  
Center console broken/parts missing

Print: David Murphy  
Date: 24/04/2017  
  
DM

CAP	
Cap Code:	E1611
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0