

# Vehicle Inspection Report

**Agreement No:**

**Reg:** VJZ3567

**CN:** VF15RRL0H49423918

Report Date: 24/04/2017 4:03PM

**NAMA Grade:** 3

Make: Renault	Fuel: D	Date First Reg: 17/10/2013
Model: Clio 1.5 D-que M-nav Energy D	Transmission: Manual	No Keepers:
Engine Size: 1.5	Gears: 5	Colour: Red
Doors: 5	Mileage: 49894	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2013	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	2
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	5
Left Front:	Other	5
Right Rear:	Michelin	6
Left Rear:	Michelin	6
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	22/08/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Lamp nsr	Broken	Replace	1	£0.00	£0.00
Bumper Rear	Cracked	Repair and Refinish	1	£111.00	£111.00
Qtr Panel nsr	Scratched	Machine Polish	1	£12.00	£12.00
Door osf	Dented	PDR Smart Repair	1	£20.00	£20.00
				Damage Cost Total:	£143.00
				Damage Cost Total (Inc VAT):	£171.60



nsr lense



rear bumper

Comments:

Print: Nicole Taylor  
Date: 21/04/2017  
*Nicole Taylor*  
*U.F.A.R.*

CAP	
Cap Code:	58077
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0