

Vehicle Inspection Report

Agreement No:

Reg: THZ2203

CN: SJNFAAZE0U6029804

Report Date: 26/04/2017 7:00PM

NAMA Grade: U

Make:	Nissan	Fuel:		Date First Reg:	31/03/2015
Model:	Leaf Acenta 3.3kw	Transmission:	Automatic	No Keepers:	1
Engine Size:	Electric	Gears:	0	Colour:	Black
Doors:	5	Mileage:	20319	Soft Top:	No
Body Type:	Hatchback	Declaration:	Not Checked	Taxi/Private Hr:	No
Vendor:	RCI Vision	Yr of Manu:	2015	Acc Damage:	No
Other:					

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Michelin	4
Left Front:	Michelin	4
Right Rear:	Michelin	3
Left Rear:	Michelin	3
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	12/04/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Unclassified	Major Parts Missing	Other	1	£0.00	£0.00
Qtr Panel osr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Scratched	Machine Polish	1	£12.00	£12.00
Door osr	Scratched	Refinish	1	£113.00	£113.00
Door osf	Dented	Refinish	1	£113.00	£113.00
Bumper Rear	Poor Previous Repair	Refinish	1	£86.00	£86.00
Door nsr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Door nsf	Dented	PDR Smart Repair	1	£20.00	£20.00
Wing osf	Dented	Refinish	1	£113.00	£113.00
Qtr Panel nsr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£505.00
				Damage Cost Total (Inc VAT):	£606.00

Comments:

FULL ELECTRIC VEHICLE 3.3kw Model *** 3.3 CHARGE CABLE MISSING ***

Print: David Murphy

Date: 19/04/2017

DM

CAP

Cap Code: 60549
 Cap Clean: 0
 Average: 0
 Below: 0
 Reserve: 0