

Vehicle Inspection Report

Agreement No:

Reg: JRZ1099

CN: SJNFAAZE0U6029618

Report Date: 10/05/2017 8:28AM

NAMA Grade: 4

Make: Nissan	Fuel:	Date First Reg: 25/03/2015
Model: Leaf Acenta - 3.3 kw	Transmission: Automatic	No Keepers: 1
Engine Size: ELECTRIC	Gears: 0	Colour: White
Doors: 5	Mileage: 30041	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	6
Left Front:	Other	6
Right Rear:	Other	7
Left Rear:	Michelin	4
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	21/04/2017
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Wing nsf	Cracked	Refinish	1	£113.00	£113.00
Wheel osf	Scratched	PDR Smart Repair	1	£20.00	£20.00
Bonnet	Poor Previous Repair	Refinish	1	£113.00	£113.00
				Damage Cost Total:	£332.00
				Damage Cost Total (Inc VAT):	£398.40



nsf wing

Comments:

FULL ELECTRIC VEHICLE 3.3kw Model, previous repairs visible

Print: nicole taylor

Date: 27/04/2017

CAP

Cap Code: 60549
 Cap Clean: 8575
 Average: 8000
 Below: 7450
 Reserve: 0