

Vehicle Inspection Report

Agreement No:

Reg: WFZ6004

CN: SJNFAAZE0U6015508

Report Date: 12/05/2017 1:53PM

NAMA Grade: 3

Make: Nissan	Fuel:	Date First Reg: 26/03/2015
Model: Leaf Acenta -3.3KW	Transmission: Automatic	No Keepers: 1
Engine Size: 0	Gears: 0	Colour: Black
Doors: 5	Mileage: 31149	Soft Top:
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		


Extras	Tyres	Miscellaneous
Cassette Stereo:	Make	Tread (mm):
CD Player: No	Right Front: Michelin	3
Sunroof:	Left Front: Michelin	3
Electric Windows: 4	Right Rear: Michelin	3
Air Conditioning: Yes	Left Rear: Michelin	3
Cruise Control: Yes	Spare: No	
Power Steering: Yes	Wheel trims:	
Alloy Wheels: Yes		
Metallic Paint: Yes		
Leather: No		
	Interior Condition	
	Clean: Odour/Smoked in?: Valet:	
	Other:	
		Service History: None
		Date Last Serviced:
		Registration Doc:
		MOT:
		Date of Expiry:
		Taxed To:
		Keys: Yes
		Master: Yes
		Spare: Yes
		No. Keys: 2



Front Angle



Rear Angle



Interior



Speedo Reading


Damage Location	Fault	Damage	Qty	Cost	Total
Qtr Panel nsr	Scratched	Machine Polish	1	£12.00	£12.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Bumper Rear	Scratched	Refinish	1	£86.00	£86.00
Sill ns	Dented	Refinish	1	£113.00	£113.00
Door osf	Scratched	Machine Polish	1	£12.00	£12.00
Door nsr	Scratched	Machine Polish	1	£12.00	£12.00
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Door nsf	Scratched	Refinish	1	£113.00	£113.00
				Damage Cost Total:	£486.00
				Damage Cost Total (Inc VAT):	£583.20



charge cable



front bumper



bumper rear



nsf wheel

Comments:

3.3kw charge cable present.sd card present,
** FULL ELECTRIC VEHICLE **

Print: nicole taylor

Date: 08/05/2017

Nicole Taylor

CAP	
Cap Code:	60549
Cap Clean:	8525
Average:	7950
Below:	7400
Reserve:	0