

# Vehicle Inspection Report

**Agreement No:** 2200183693

**Reg:** VNZ1226

**CN:** SJNFAAZE0U6027974

Report Date: 12/05/2017 1:50PM

**NAMA Grade:** 1

Make: Nissan	Fuel:	Date First Reg: 31/03/2015
Model: Leaf Acenta -6.6KW	Transmission: Automatic	No Keepers:
Engine Size:	Gears:	Colour: Red
Doors: 5	Mileage: 19110	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Contract Hire	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Michelin	3
Left Front:	Michelin	3
Right Rear:	Michelin	2
Left Rear:	Michelin	3
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	20/01/2017
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bumper Rear	Scratched	Machine Polish	1	£12.00	£12.00
Qtr Panel osr	Scratched	Machine Polish	1	£12.00	£12.00
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
Qtr Panel nsr	Scratched	Machine Polish	1	£12.00	£12.00
				Damage Cost Total:	£100.00
				Damage Cost Total (Inc VAT):	£120.00

Comments:

s sdCARD here cable in boot,  
 \*\* FULL ELECTRIC VEHICLE \*\* 6.6KW MODEL \*\*

Print: david moore

Date: 02/05/2017



CAP

Cap Code: 60549  
 Cap Clean: 9175  
 Average: 8550  
 Below: 7950  
 Reserve: 0