

# Vehicle Inspection Report

**Agreement No:** 2100021689

**Reg:** SFZ4094

**CN:** VF12RFA1H49534081

Report Date: 10/05/2017 2:27PM

**NAMA Grade:** 1

Make: Renault	Fuel: P	Date First Reg: 29/03/2014
Model: Captur 0.9 D-que M-nav Nrg Tc	Transmission: Manual	No Keepers: 1
Engine Size: 0.9	Gears: 5	Colour: Black
Doors: 5	Mileage: 24899	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Voluntary Terminations	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	7
Left Front:	Other	7
Right Rear:	Michelin	4
Left Rear:	Michelin	4
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	31/05/2016
Registration Doc:	
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Wing nsf	Scratched	Machine Polish	1	£12.00	£12.00
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
Bumper Front	Scratched	Machine Polish	1	£12.00	£12.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
Door osf	Dented	PDR Smart Repair	1	£20.00	£20.00
				Damage Cost Total:	£96.00
				Damage Cost Total (Inc VAT):	£115.20



osf wheel

Comments:

Print: nicole taylor  
Date: 10/05/2017  
*Nicole Taylor*

CAP	
Cap Code:	60777
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0