

Vehicle Inspection Report

Agreement No:

Reg: LMN421X

CN: MDHFBUK13U0799819Y

Report Date: 12/05/2017 1:47PM

NAMA Grade: 4

Make: Nissan	Fuel: P	Date First Reg: 01/04/2015
Model: Micra Acenta -	Transmission: Manual	No Keepers:
Engine Size:	Gears: 5	Colour:
Doors: 5	Mileage: 25687	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu:	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	2
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	3
Left Front:	Other	5
Right Rear:	Bridgestone	5
Left Rear:	Bridgestone	5
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	None
Date Last Serviced:	
Registration Doc:	None
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading


Damage Location	Fault	Damage	Qty	Cost	Total
Bonnet	Dented	PDR Smart Repair	1	£20.00	£20.00
Bumper Rear	Poor Previous Repair	Refinish	1	£86.00	£86.00
Door nsf	Poor Previous Repair	Refinish	1	£113.00	£113.00
Door nsr	Poor Previous Repair	Refinish	1	£113.00	£113.00
Tailgate	Poor Previous Repair	Refinish	1	£113.00	£113.00
Carpets Front	Holed	Interior Smart Repair	1	£40.00	£40.00
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
Qtr Panel nsr	Poor Previous Repair	Refinish	1	£113.00	£113.00
Wing nsf	Poor Previous Repair	Refinish	1	£113.00	£113.00
				Damage Cost Total:	£723.00
				Damage Cost Total (Inc VAT):	£867.60



drivers carpets

Comments:
previous repairs visible

Print: David Murphy
Date: 12/05/2017



CAP	
Cap Code:	61925
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0