

Vehicle Inspection Report

Agreement No:

Reg: LMN267X

CN: SJNTAAE12U1097889L

Report Date: 12/05/2017 1:42PM

NAMA Grade: 2

Make: Nissan	Fuel: P	Date First Reg: 01/04/2015
Model: Note Acenta -	Transmission: Manual	No Keepers:
Engine Size:	Gears: 5	Colour: blue
Doors: 5	Mileage: 20603	Soft Top: No
Body Type: MPV	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu:	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	4
Left Front:	Other	4
Right Rear:	Continental	5
Left Rear:	Continental	5
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	None
Date Last Serviced:	
Registration Doc:	None
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Tailgate	Dented	PDR Smart Repair	1	£20.00	£20.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Tailgate	Dented	PDR Smart Repair	1	£20.00	£20.00
Door nsr	Scratched	Refinish	1	£113.00	£113.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Wing nsf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£291.00
				Damage Cost Total (Inc VAT):	£349.20



FRONT BUMPER



nsf wheel

Comments:
oil filler cap missing

Print: David Murphy
Date: 12/05/2017

DM

CAP	
Cap Code:	61907
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0