

Vehicle Inspection Report

Agreement No: 2200032439

Reg: RHZ2470

CN: SJNFAAZE0U6000028

Report Date: 12/05/2017 5:38PM

NAMA Grade: 3

Make: Nissan	Fuel:	Date First Reg: 31/05/2013
Model: Leaf Tekna - 3.3kw	Transmission: Automatic	No Keepers: 1
Engine Size: 0	Gears: 0	Colour: Grey
Doors: 5	Mileage: 36110	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Contract Hire	Yr of Manu: 2013	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	Yes

Tyres		
	Make	Tread (mm):
Right Front:	Other	3
Left Front:	Other	3
Right Rear:	Other	6
Left Rear:	Other	5
Spare:		
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	31/05/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Wing osf	Scratched	Machine Polish	1	£12.00	£12.00
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
Door Mirror Assy osf	Broken	Replace	1	£0.00	£0.00
Bumper Rear	Chipped	Refinish	1	£86.00	£86.00
Door nsf	Scratched	Machine Polish	1	£12.00	£12.00
Door nsr	Scratched	Refinish	1	£113.00	£113.00
Door osf	Scratched	Machine Polish	1	£12.00	£12.00
Qtr Panel nsr	Scratched	Refinish	1	£113.00	£113.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
				Damage Cost Total:	£446.00
				Damage Cost Total (Inc VAT):	£535.20




charge cable



nsr door



nsr qrt



bumper rear

Comments:

FULL ELECTRIC VEHICLE 3.3kw charge cable present,sd card present.

Print: nicole taylor

Date: 12/05/2017

Nicole Taylor

CAP

Cap Code:	60550
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0