

# Vehicle Inspection Report

**Agreement No:**

**Reg:** SFZ8240

**CN:** VF12RFL1H50240130

Report Date: 26/05/2017 5:35PM

**NAMA Grade:** 1

Make:	Renault	Fuel:	D	Date First Reg:	30/05/2014
Model:	Capturd-que 1.5 M-nav Energy	Transmission:	Manual	No Keepers:	1
Engine Size:	1.5	Gears:	5	Colour:	Orange And Blac
Doors:	5	Mileage:	16165	Soft Top:	No
Body Type:	Hatchback	Declaration:	Not Checked	Taxi/Private Hr:	No
Vendor:	RCI Vision	Yr of Manu:	2014	Acc Damage:	No
Other:					


Extras		Tyres		Miscellaneous		
Cassette Stereo:	No	Make	Tread (mm):	Service History:	Full	
CD Player:	No	Right Front:	Michelin	3	Date Last Serviced:	28/03/2017
Sunroof:		Left Front:	Michelin	4	Registration Doc:	Here
Electric Windows:	4	Right Rear:	Michelin	5	MOT:	
Air Conditioning:	Yes	Left Rear:	Millennium	4	Date of Expiry:	
Cruise Control:	Yes	Spare:	No	Taxed To:		
Power Steering:	Yes	Wheel trims:		Keys:	Yes	
Alloy Wheels:	Yes			Master:	Yes	
Metallic Paint:	Yes			Spare:	Yes	
Leather:	No			No. Keys:	2	



**Front Angle**



**Rear Angle**




**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Door nsf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Door nsf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Qtr Panel nsr	Scratched	Machine Polish	1	£12.00	£12.00
				Damage Cost Total:	£76.00
				Damage Cost Total (Inc VAT):	£91.20

Comments:

Print: nicole taylor  
Date: 22/05/2017  


CAP	
Cap Code:	60783
Cap Clean:	8150
Average:	7625
Below:	7100
Reserve:	0