

# Vehicle Inspection Report

**Agreement No:**

**Reg:** BGZ7293

**CN:** VF1BZ890H55036308

Report Date: 21/06/2017 11:24AM

**NAMA Grade:** 3

Make: Renault	Fuel: D	Date First Reg: 31/03/2016
Model: Megane 1.5 Dynamique Nav Dci	Transmission: Manual	No Keepers: 1
Engine Size: 1.5	Gears: 6	Colour: Silver
Doors: 5	Mileage: 18999	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2016	Acc Damage: No
Other:		


Extras	Tyres	Miscellaneous
Cassette Stereo: No	Make	Service History: Full
CD Player: Yes	Tread (mm):	Date Last Serviced:
Sunroof:	Right Front: Other 7	Registration Doc: Here
Electric Windows: 4	Left Front: Other 7	MOT:
Air Conditioning: Yes	Right Rear: Michelin 5	Date of Expiry:
Cruise Control: Yes	Left Rear: Michelin 5	Taxed To:
Power Steering: Yes	Spare: No	Keys: Yes
Alloy Wheels: Yes	Wheel trims:	Master: Yes
Metallic Paint: Yes	Interior Condition	Spare: Yes
Leather: Yes	Clean: Odour/Smoked in?: No Valet:	No. Keys: 2
	Other:	



**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Rear	Scratched	Machine Polish	1	£12.00	£12.00
Roof	Scratched	Machine Polish	1	£12.00	£12.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Qtr Panel nsr	Dented	Refinish	1	£113.00	£113.00
C Post os	Scratched	Machine Polish	1	£12.00	£12.00
B Post ns	Scratched	Machine Polish	1	£12.00	£12.00
Door osf	Dented	Refinish	1	£113.00	£113.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Bonnet	Dented	Repair and Refinish	1	£138.00	£138.00
				Damage Cost Total:	£538.00
				Damage Cost Total (Inc VAT):	£645.60



**bonnet**



**bumper front**



**nsf wheel**



**osf door**

Comments:

SD CARD PRESENT

Print: Nicole taylor

Date: 15/06/2017

*Nicole Taylor*

CAP

Cap Code:	69082
Cap Clean:	7300
Average:	6775
Below:	6275
Reserve:	0