

# Vehicle Inspection Report

**Agreement No:**

**Reg:** RFZ4802

**CN:** VF12RFA1H49534128

Report Date: 23/06/2017 8:25AM

**NAMA Grade:** 2

Make: Renault	Fuel: P	Date First Reg: 14/02/2014
Model: Captur 0.9 D-que M-nav Nrg Tc	Transmission: Manual	No Keepers:
Engine Size: 0.9	Gears: 5	Colour: Black
Doors: 5	Mileage: 35618	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Goodyear	5
Left Front:	Michelin	3
Right Rear:	Michelin	2
Left Rear:	Michelin	2
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	29/12/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Door osr	Dented	PDR Smart Repair	1	£20.00	£20.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
Door osf	Dented	PDR Smart Repair	1	£20.00	£20.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Qtr Panel nsr	Dented	PDR Smart Repair	1	£20.00	£20.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£238.00
				Damage Cost Total (Inc VAT):	£285.60




**osf wheel**



**front bumper**

Comments:

Print: David Murphy  
Date: 16/06/2017  


CAP	
Cap Code:	60777
Cap Clean:	6725
Average:	6250
Below:	5775
Reserve:	0