

Vehicle Inspection Report

Agreement No: 2100047106

Reg: GXZ4126

CN: VF12RFA1H51179207

Report Date: 20/06/2017 6:57PM

NAMA Grade: 1

Make: Renault	Fuel: P	Date First Reg: 31/07/2014
Model: Captur D-que 0.9 M-nav Nrg Tc	Transmission: Manual	No Keepers: 1
Engine Size: 0.9	Gears: 5	Colour: Blue And Black
Doors: 5	Mileage: 33005	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Voluntary Terminations	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	4
Left Front:	Other	6
Right Rear:	Other	6
Left Rear:	Other	6
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Front	Scratched	Machine Polish	1	£12.00	£12.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£52.00
				Damage Cost Total (Inc VAT):	£62.40

Comments:

Print: nicole taylor
Date: 20/06/2017
Nicole Taylor

CAP	
Cap Code:	60777
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0