

Vehicle Inspection Report

Agreement No: 2100128331

Reg: WFZ9726

CN: VF15RRL0H52802144

Report Date: 27/06/2017 5:19PM

NAMA Grade: 1

| | | |
|--------------------------------------|--------------------------|----------------------------|
| Make: Renault | Fuel: D | Date First Reg: 30/04/2015 |
| Model: Clio D-que 1.5 M-nav Energy D | Transmission: Manual | No Keepers: 1 |
| Engine Size: 1.5 | Gears: 5 | Colour: White |
| Doors: 5 | Mileage: 42565 | Soft Top: No |
| Body Type: Hatchback | Declaration: Not Checked | Taxi/Private Hr: No |
| Vendor: RCI Voluntary Terminations | Yr of Manu: 2015 | Acc Damage: No |
| Other: | | |


| Extras | Tyres | Miscellaneous |
|-----------------------|------------------------------------|--------------------------------|
| Cassette Stereo: No | Make | Service History: Full |
| CD Player: Yes | Tread (mm): | Date Last Serviced: 02/02/2017 |
| Sunroof: | Right Front: Other 6 | Registration Doc: Here |
| Electric Windows: 2 | Left Front: Other 6 | MOT: |
| Air Conditioning: Yes | Right Rear: Michelin 6 | Date of Expiry: |
| Cruise Control: Yes | Left Rear: Michelin 5 | Taxed To: |
| Power Steering: Yes | Spare: No | Keys: Yes |
| Alloy Wheels: Yes | Wheel trims: | Master: Yes |
| Metallic Paint: No | Interior Condition | Spare: Yes |
| Leather: No | Clean: Odour/Smoked in?: No Valet: | No. Keys: 2 |
| | Other: | |




Front Angle



Rear Angle




Interior



Speedo Reading

| Damage Location | Fault | Damage | Qty | Cost | Total |
|-----------------|-----------|-----------------------|-----|------------------------------|---------|
| Door nsr | Scratched | Refinish | 1 | £113.00 | £113.00 |
| Bumper Front | Scratched | Touch In Smart Repair | 1 | £12.00 | £12.00 |
| | | | | Damage Cost Total: | £125.00 |
| | | | | Damage Cost Total (Inc VAT): | £150.00 |



nsr door

Comments:

Print: nicole taylor
Date: 27/06/2017
Nicole Taylor

| CAP | |
|------------|-------|
| Cap Code: | 58077 |
| Cap Clean: | 0 |
| Average: | 0 |
| Below: | 0 |
| Reserve: | 0 |