

Vehicle Inspection Report

Agreement No: 2100036781

Reg: SHZ4782

CN: VF12RFL1H50618218

Report Date: 30/06/2017 2:58PM

NAMA Grade: 3

Make: Renault	Fuel: D	Date First Reg: 25/06/2014
Model: Captur-que 1.5 M-nav Energy	Transmission: Manual	No Keepers:
Engine Size: 1.5	Gears: 5	Colour: Cream
Doors: 5	Mileage: 29839	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	2
Left Front:	Other	3
Right Rear:	Other	6
Left Rear:	Other	6
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	No
No. Keys:	1




Front Angle



Rear Angle



Interior



Speedo Reading


Damage Location	Fault	Damage	Qty	Cost	Total
C Post ns	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
Door Mirror Assy osf	Broken	Replace	1	£0.00	£0.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Wheel osr	Scratched	Refinish	1	£40.00	£40.00
Door nsf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Carpets Front	Holed	Interior Smart Repair	1	£40.00	£40.00
Qtr Panel osr	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£248.00
				Damage Cost Total (Inc VAT):	£297.60



nsf WHEEL



osf wheel



drivers carpets

Comments:

Print: David Murphy
Date: 30/06/2017

CAP	
Cap Code:	60783
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0