

Vehicle Inspection Report

Agreement No:

Reg: XJZ3313

CN: SJNFAAZE0U6031673

Report Date: 07/07/2017 8:25AM

NAMA Grade: 2

Make: Nissan	Fuel:	Date First Reg: 29/05/2015
Model: Leaf Tekna -3.3 kw model	Transmission: Automatic	No Keepers:
Engine Size: ELECTRIC	Gears:	Colour: Red
Doors: 5	Mileage: 20335	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2015	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	Yes

Tyres		
	Make	Tread (mm):
Right Front:	Other	5
Left Front:	Other	5
Right Rear:	Dunlop	2
Left Rear:	Dunlop	2
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: Yes	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	24/06/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Tailgate	Scratched	Refinish	1	£113.00	£113.00
Bumper Rear	Scratched	Refinish	1	£86.00	£86.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Qtr Panel nsr	Scratched	Machine Polish	1	£12.00	£12.00
Door osr	Scratched	Machine Polish	1	£12.00	£12.00
Door nsr	Scratched	Machine Polish	1	£12.00	£12.00
				Damage Cost Total:	£275.00
				Damage Cost Total (Inc VAT):	£330.00



3 kw charge cable



rear bumper

Comments:
 FULL ELECTRIC VEHICLE 3.3kw Model, nsr seatbelt damaged

Print: David Murphy
 Date: 05/07/2017

DM

CAP	
Cap Code:	60550
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0