

# Vehicle Inspection Report

**Agreement No:**

**Reg:** SN64BSO

**CN:** W0LGS6ES6F1012919

**Report Date:** 07/07/2017 8:26AM

**NAMA Grade:** 3

Make:	Vauxhall	Fuel:	D	Date First Reg:	04/02/2015
Model:	Insignia 2.0 CDTi Sri Ecoflex	Transmission:	Manual	No Keepers:	2
Engine Size:	2.0	Gears:	6	Colour:	White
Doors:	5	Mileage:	41829	Soft Top:	No
Body Type:	Hatchback	Declaration:	Not Checked	Taxi/Private Hr:	No
Vendor:	RCI Vision	Yr of Manu:	2015	Acc Damage:	No
Other:					


Extras		Tyres		Miscellaneous	
Cassette Stereo:	No	Make	Tread (mm):	Service History:	Full
CD Player:	Yes	Right Front: Other	3	Date Last Serviced:	02/02/2017
Sunroof:		Left Front: Other	3	Registration Doc:	Here
Electric Windows:	4	Right Rear: Continental	3	MOT:	
Air Conditioning:	Yes	Left Rear: Continental	3	Date of Expiry:	
Cruise Control:	Yes	Spare:		Taxed To:	
Power Steering:	Yes	Wheel trims:		Keys:	Yes
Alloy Wheels:	Yes			Master:	Yes
Metallic Paint:	No			Spare:	Yes
Leather:	No			No. Keys:	2




**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Bumper Rear	Dented	Refinish	1	£86.00	£86.00
Sill ns	Dented	Refinish	1	£113.00	£113.00
Bumper Front	Dented	Repair and Refinish	1	£111.00	£111.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£350.00
				Damage Cost Total (Inc VAT):	£420.00




front bumper



rear bumper

Comments:

Print: David Murphy  
Date: 06/07/2017  


CAP	
Cap Code:	61434
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0