

# Vehicle Inspection Report

**Agreement No:**

**Reg:** MIG2372

**CN:** VF15R0G0H48801144

Report Date: 17/07/2017 8:54AM

**NAMA Grade:** 2

Make: Renault	Fuel: P	Date First Reg: 31/01/2014
Model: Clio 1.2 Dynamique Medianav	Transmission: Manual	No Keepers:
Engine Size: 1.2	Gears: 5	Colour: Yellow
Doors: 5	Mileage: 23108	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	2
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	5
Left Front:	Other	5
Right Rear:	Continental	5
Left Rear:	Continental	5
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		

Miscellaneous	
Service History:	Full
Date Last Serviced:	25/01/2017
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



**Front Angle**



**Rear Angle**



**Interior**



**Speedo Reading**

Damage Location	Fault	Damage	Qty	Cost	Total
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Bumper Rear	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Qtr Panel nsr	Scratched	Machine Polish	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel osr	Scratched	Refinish	1	£40.00	£40.00
Door osf	Dented	PDR Smart Repair	1	£20.00	£20.00
Door nsf	Dented	PDR Smart Repair	1	£20.00	£20.00
Door Mirror Assy osf	Scratched (Painted)	Other	1	£0.00	£0.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£248.00
				Damage Cost Total (Inc VAT):	£297.60



osf wheel



plastic mirror



osr wheel

Comments:

Print: David Murphy  
Date: 11/07/2017

CAP	
Cap Code:	58071
Cap Clean:	0
Average:	0
Below:	0
Reserve:	0