

Vehicle Inspection Report

Agreement No:

Reg: TFZ8699

CN: VF12RFA1H51136692

Report Date: 02/08/2017 5:39PM

NAMA Grade: 2

Make: Renault	Fuel: P	Date First Reg: 31/07/2014
Model: Captur 0.9 D-que M-nav Nrg Tc	Transmission: Manual	No Keepers:
Engine Size: 0.9	Gears: 5	Colour: Grey And Black
Doors: 5	Mileage: 23944	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	6
Left Front:	Other	6
Right Rear:	Michelin	4
Left Rear:	Michelin	4
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	07/07/2017
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Door nsr	Dented	PDR Smart Repair	1	£20.00	£20.00
Bumper Front	Scratched	Refinish	1	£86.00	£86.00
Door nsf	Dented	PDR Smart Repair	1	£20.00	£20.00
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£166.00
				Damage Cost Total (Inc VAT):	£199.20



front bumper



nsr door

Comments:

Print: David Murphy
Date: 24/07/2017
DM

CAP	
Cap Code:	60777
Cap Clean:	7275
Average:	6775
Below:	6275
Reserve:	0