

Vehicle Inspection Report

Agreement No:

Reg: GXZ2959

CN: VF12RFL1H50617964

Report Date: 11/08/2017 5:45PM

NAMA Grade: 1

Make: Renault	Fuel: D	Date First Reg: 20/06/2014
Model: Capturd-que 1.5 M-nav Energy	Transmission: Manual	No Keepers:
Engine Size: 1.5	Gears: 5	Colour: Blue
Doors: 5	Mileage: 13430	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	5
Left Front:	Other	5
Right Rear:	Michelin	4
Left Rear:	Michelin	4
Spare:	No	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



Front Angle



Rear Angle



Interior




Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Door osr	Dented	PDR Smart Repair	1	£20.00	£20.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Door Mirror Assy nsf	Scratched (Painted)	Other	1	£0.00	£0.00
				Damage Cost Total:	£44.00
				Damage Cost Total (Inc VAT):	£52.80

Comments:

Print: David Murphy
Date: 08/08/2017



CAP	
Cap Code:	60783
Cap Clean:	8100
Average:	7550
Below:	7050
Reserve:	0