

Vehicle Inspection Report

Agreement No:

Reg: GXZ5299

CN: VF12RFA1H51486487

Report Date: 11/08/2017 5:42PM

NAMA Grade: 2

Make: Renault	Fuel: P	Date First Reg: 19/08/2014
Model: Captur-que 0.9 S M-nav Nrg T	Transmission: Manual	No Keepers:
Engine Size: 0.9	Gears: 5	Colour: Blue And Black
Doors: 5	Mileage: 29743	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2014	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	No
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	Yes
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	5
Left Front:	Other	5
Right Rear:	Michelin	3
Left Rear:	Michelin	3
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	16/09/2016
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2




Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty	Cost	Total
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Door nsr	Dented	PDR Smart Repair	1	£20.00	£20.00
Door osf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
Bonnet	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Bumper Front	Chipped	Touch In Smart Repair	1	£12.00	£12.00
				Damage Cost Total:	£136.00
				Damage Cost Total (Inc VAT):	£163.20

Comments:

Print: David Murphy
Date: 09/08/2017

DM

CAP	
Cap Code:	60778
Cap Clean:	7600
Average:	7075
Below:	6575
Reserve:	0