

Vehicle Inspection Report

Agreement No:

Reg: PFZ8180

CN: VF12RFA1H49608804

Report Date: 11/08/2017 5:43PM

NAMA Grade: 2

Make: Renault	Fuel: P	Date First Reg: 29/11/2013
Model: Capture 0.9 xpr-n+conv-ce Nrg	Transmission: Manual	No Keepers:
Engine Size: 0.9	Gears: 5	Colour: Cream
Doors: 5	Mileage: 28843	Soft Top: No
Body Type: Hatchback	Declaration: Not Checked	Taxi/Private Hr: No
Vendor: RCI Vision	Yr of Manu: 2013	Acc Damage: No
Other:		

Extras	
Cassette Stereo:	No
CD Player:	Yes
Sunroof:	
Electric Windows:	4
Air Conditioning:	Yes
Cruise Control:	Yes
Power Steering:	Yes
Alloy Wheels:	Yes
Metallic Paint:	No
Leather:	No

Tyres		
	Make	Tread (mm):
Right Front:	Other	4
Left Front:	Other	4
Right Rear:	Bridgestone	3
Left Rear:	Bridgestone	3
Spare:	Yes	
Wheel trims:		

Interior Condition		
Clean:	Odour/Smoked in?: No	Valet:
Other:		


Miscellaneous	
Service History:	Full
Date Last Serviced:	19/07/2017
Registration Doc:	Here
MOT:	
Date of Expiry:	
Taxed To:	
Keys:	Yes
Master:	Yes
Spare:	Yes
No. Keys:	2



Front Angle



Rear Angle



Interior



Speedo Reading


Damage Location	Fault	Damage	Qty	Cost	Total
A Post os	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel osf	Scratched	Refinish	1	£40.00	£40.00
Wing Front Arch Extension ns	Scuffed (Unpainted)	Other	1	£0.00	£0.00
Roof Lining	Soiled	Interior Smart Repair	1	£40.00	£40.00
Bumper Front	Scratched	Touch In Smart Repair	1	£12.00	£12.00
Wheel nsf	Scratched	Refinish	1	£40.00	£40.00
Door nsf	Dented	PDR Smart Repair	1	£20.00	£20.00
Door osr	Dented	PDR Smart Repair	1	£20.00	£20.00
Door osf	Chipped	Touch In Smart Repair	1	£12.00	£12.00
Wheel nsr	Scratched	Refinish	1	£40.00	£40.00
				Damage Cost Total:	£236.00
				Damage Cost Total (Inc VAT):	£283.20



nsf door



nsr door



os A post

Comments:

seats soiled need of through vallet , rear boot divider missing

Print: David Murphy

Date: 09/08/2017

CAP

Cap Code:	60776
Cap Clean:	6225
Average:	5775
Below:	5350
Reserve:	0